SHELTER ISLAND ID#60

CORE # = 1

DATE = 5/5/06 NOTE: MEASUREMENTS GIVEN IN FEET

TIME = 12:00pm

WATER DEPTH = 0.0

PENETRATING DEPTH = 8.8ft

CORE (RECOVERY) = Auger = 2.3ft / Piston = 5.8ft

STRATIGRAPHY NOTES:

OVERALL RESULTS: PERCENT SILT/CLAY = 4.0%

PERCENT SAND = 96.0%

Note: Percents were calculated compositing 1 surface

sample from Site#1 as well as the Core from

Site#1 at CDF ID#60.

NOTE: NOT TO SCALE

В	5.8ft Sand (Grey) w/Iron Stains	2.3ft Sand (Grey)
---	---------------------------------------	-------------------------